

This form is used to describe how the accident happened. It does not mean that anyone admits liability. Please have it completed by both drivers.

1. Date of accident

2026-05-14

Time

17:20

2. Place

Heyd?r ?liyev prospekti 31, Baki, AZ

VEHICLE A

6. Policyholder/Insured

(see insurance certificate)

Surname

M?mm?dov

First name

?li

Address

Heyd?r ?liyev prospekti 31, Baki

Postcode

AZ1033

Country

AZ

Phone/ email

+994 50 123 45 67

7.1 Motor vehicle

Make, type

Hyundai Tucson

Registration number

90-AB-447

Country of registration

AZ

7.2 Trailer

Registration number

Country of registration

8. Insurance company

(see insurance certificate)

Company name

PASA Sigorta ASC

Policy number

AZ-2026-114770

Green Card number

AZ/26/114770

Insurance certificate/Green Card valid

from

2026-01-01

to

2026-12-31

Agency (office or broker)

Name

Address

Sahil Plaza, M. Huseynov kuc. 61, AZ1095 Baki

Postcode

Country

Phone/ email

Is damage to the vehicle insured under the policy?

☐ no

☒ yes

9. Driver

(see driving licence)

Surname

M?mm?dov

First name

?li

Date of birth

1982-09-30

Address

Heyd?r ?liyev prospekti 31, Baki

Postcode

AZ1033

Country

AZ

Phone/ email

+994 50 123 45 67, ali.mammadov@example.com

Driving licence no.

AZ 8842130


Category (A,B,...)

B

Licence valid until

2029-09-30

10. Indicate with an arrow the point of initial impact on vehicle A



11. Visible damage to vehicle A

14. Remarks

Heyd?r ?liyev prospekti boyunca yol ayricindan duz

kecidim, sag zolaqda, t?xmin?n 40 km/saat sur?tl?. B (...)

3. Injuries

Injured/slightly injured?

☒ no

☐ yes

4. Material damage

to vehicles other than A and B

☒ no

☐ yes

to objects other than vehicles

☒ no

☐ yes

12. Circumstances

Put a cross in each box that applies, to help explain the sketch. Cross out anything that does not apply.

A

01

☐

was parked / was stationary

02

☐

was leaving a parking place / was opening a car door

03

☐

was pulling into a parking place

04

☐

was leaving a car park, private property or a track

05

☐

was entering a car park, private property or a track

06

☐

was entering a roundabout

07

☐

was driving on a roundabout

08

☐

struck the rear of the other vehicle while going in the same direction and in the same lane

09

☐

was going in the same direction, but in a different lane

10

☐

was changing lanes

11

☐

was overtaking

12

☐

was turning right

13

☐

was turning left

14

☐

was reversing

15

☐

was crossing into the oncoming lane

16

☐

was coming from the right (at a junction)

17

☐

had ignored a priority sign or a red light

☐

Enter the number of boxes marked with a cross.

B

01

☐

02

☐

03

☐

04

☐

05

☐

06

☐

07

☐

08

☐

09

☐

10

☐

11

☐

12

☐

13

☐

14

☐

15

☐

16

☒


17

☒

2

13. Sketch of the accident at the moment of impact

Please show: 1. the lane layout 2. the direction of travel of vehicles A and B (with arrows) 3. their position at the moment of impact 4. road signs 5. street names



Both drivers must sign. Signing does not mean admitting liability - it only confirms the personal details and the description of the accident, which speeds up the claims process.

15. Signatures of both drivers



A



B

5. Witnesses

(underline passengers)

Names, addresses, phone numbers

Aysel Quliyeva, +994 50

100 01 11

VEHICLE B

6. Policyholder/Insured

(see insurance certificate)

Surname

Yilmaz

First name

Ahmet

Address

Bagdat Caddesi 198, Istanbul

Postcode

34726

Country

TR

Phone/ email

+90 532 123 45 67

7.1 Motor vehicle

Make, type

Renault Megane

Registration number

34 AB 4471

Country of registration

TR

7.2 Trailer

Registration number

Country of registration

8. Insurance company

(see insurance certificate)

Company name

Anadolu Anonim Turk Sigorta Sirketi

Policy number

TR-2026-551083

Green Card number

TR/26/551083

Insurance certificate/Green Card valid

from

2026-02-01

to

2027-01-31

Agency (office or broker)

Name

Address

Ruzgaribahce Mah. Cam Pinarı Sok. No: 6, 34805 Beykoz/Istanbul

Postcode

Country

Phone/ email

Is damage to the vehicle insured under the policy?

☒ no

☐ yes

9. Driver

(see driving licence)

Surname

Yilmaz

First name

Ahmet

Date of birth

1981-06-18

Address

Bagdat Caddesi 198, Istanbul

Postcode

34726

Country

TR

Phone/ email

+90 532 123 45 67, ahmet.yilmaz@example.com

Driving licence no.

TR 8842130


Category (A,B,...)

B

Licence valid until

2030-06-18

10. Indicate with an arrow the point of initial impact on vehicle B



11. Visible damage to vehicle B

14. Remarks

Heyd?r ?liyev prospekti kavsagina sagdan, tali yoldan

yaklasiyordum. A aracini cok gec fark ettim ve gecis hakki (...)

easf.eu

| European Accident Statement

English

Annex - additional details

14. Notes (optional) (A)

Heydər Əliyev prospekti boyunca yol ayrıcından düz keçirdim, sağ zolaqda, təxminən 40 km/saat sürətlə. B nəqliyyat vasitəsi sağdan gələn və yol vermədi. Sağ ön qanad, bəmper və sağ far zədələnib.

14. Notes (optional) (B)

Heydər Əliyev prospekti kəvsəsinə sağdan, tək yoldan yaxlaşıyordum. A aracını çox gec fark etdim və gecikmə haqqı vermedim. Sol yan, ön kapı hızasında hasar gördü. Kusuru qabul ediyorum.